

10/27/2023

FOR YOUR INFORMATION

2023-176/11-36

To: Airport Manager, Chicago O'Hare Int'l, (ORD), FAA (AAS-1), Jeppesen Sanderson Inc. 2034807


Info: FAA (Director of Air Traffic Operations CSA, ATM ORD ATCT, AAS-300, AVP-1, AVP-200, AGL-600, AFS-260, AFS-200, AJI-144, Runway Safety Team), A4A, AAAE, ALPA, AOPA, APA, ASAP, ATSAP, ATSG, CAPA, IATA, ICASS, IFALPA, IPA, NATCA, NBAA, NTSB, RAA, SWAPA

From: Becky L. Hooey, Director
NASA Aviation Safety Reporting System

Re: ORD Airport Runway/ILS Hold Short Lines

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.



Aviation Safety Reporting System
P.O. Box 189 | Moffett Field, CA | 94035-0189



ACN 2034807

DATE / TIME

Date of Occurrence	202309
Local Time Of Day	0601 to 1200

PLACE

Locale	ORD.Airport
State	IL

AIRCRAFT / EQUIPMENT X

ATC / Advisory - Tower	ORD
Make Model Name	Any Unknown or Unlisted Aircraft Manufacturer
Operating Under FAR Part	91

PERSON 1

Function - Flight Crew	Captain
ASRS Report Number	2034807

EVENTS

Anomaly	Ground Event / Encounter - Other / Unknown
Detector - Person	Flight Crew
Result - Flight Crew	Requested ATC Assistance / Clarification

NARRATIVE 1

Approaching Runway 28R at ORD we encountered these hold short lines on Taxiway V between V6 and V7. The multi function display marks it as a runway hold line, but ORD Ground Control says it's an ILS hold, which is a different marking.

SYNOPSIS

Pilot reported ILS hold short lines on Taxiway V approaching Runway 28R at ORD are depicted as runway hold lines on their multi function display. Reportedly, the lines on the taxiway are ILS hold lines.