

12/29/2023

**FOR YOUR INFORMATION**

2023-217/5-73

To: Airport Manager, Chicago O'Hare Int'l, (ORD), FAA (AAS-1)

2051625

Info: FAA (Director of Air Traffic Operations CSA, ATM ORD ATCT, AAS-300, AVP-1, AVP-200, AGL-600, AFS-260, AFS-200, AJI-144, Runway Safety Team), A4A, AAAE, ALPA, AOPA, APA, ASAP, ATSAP, ATSG, CAPA, IATA, ICASS, IFALPA, IPA, NATCA, NBAA, NTSB, RAA, SWAPA

From: Becky L. Hooey, Director  
NASA Aviation Safety Reporting System

Re: ORD Taxiway Condition

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at [becky.l.hooey@nasa.gov](mailto:becky.l.hooey@nasa.gov).



Aviation Safety Reporting System  
P.O. Box 189 | Moffett Field, CA | 94035-0189



## ACN 2051625

### DATE / TIME

Date of Occurrence 202311  
Local Time Of Day No Local Time Of Day Stated

### PLACE

Locale ORD.Airport  
State IL  
Altitude - AGL 0

### AIRCRAFT / EQUIPMENT X

Make Model Name No Aircraft  
Operating Under FAR Part 121

### PERSON 1

Function - Ground Personnel Ramp  
ASRS Report Number 2051625

### EVENTS

Anomaly No Specific Anomaly Occurred - Unwanted Situation  
Detector - Person Ground Personnel  
Result - General None Reported / Taken

### NARRATIVE 1

The northernmost crossing point between Terminals 3 and 5, located between taxiways A20 and A21 and crossing taxiways A and B, has multiple large bumps directly on the Taxiway A surface, at the southern half of the service road crossing. These bumps pose a significant hazard for both ramp vehicles and aircraft.

### CALLBACK 1

Reporter stated location was ORD airport.

### SYNOPSIS

Ramp Agent reported there are multiple large bumps on an ORD taxiway that pose a hazard to ramp vehicles and aircraft.