12/6/2024 **FOR YOUR INFORMATION** 2024-226/8-17

To: Airport Manager, John Wayne-Orange County Airport, (SNA), CA, FAA

2180991

(ATM SCT TRACON, AAS-1)

Info: FAA (Director of Air Traffic Operations WSA, AAS-300, AVP-1, AVP-200, AWP-600, AFS-260, AFS-200, AJI-144), A4A, AAAE, ALPA, AOPA, APA, ASAP, ATSAP, ATSG,

CAPA IATA, ICASS, IFALPA, IPA, NATCA, NBAA, NTSB, RAA, SWAPA

From: Becky L. Hooey, Director

NASA Aviation Safety Reporting System

Re: SCT TRACON SNA Departure Speed Assignments

We recently received ASRS reports describing a safety concern that may involve your area of operational responsibility. We do not have sufficient details to assess either the factual accuracy or possible gravity of the report. It is our policy to relay the reported information to the appropriate authority for evaluation and any necessary follow-up. We feel you should be aware of the enclosed deidentified report.

To properly assess the usefulness of our alert message service, we would appreciate it if you would take the time to give us your feedback on the value of the information that we have provided. Please contact Dr. Becky Hooey at (408) 541-2854 or email at becky.l.hooey@nasa.gov.





ACN 2180991		
DATE / TIME		
Date of Occurrence Local Time Of Day	202410 No Local Time Of Day Stated	
PLACE		
Locale State Altitude - MSL ENVIRONMENT	SCT.TRACON CA 6000	
Flight Conditions	VMC	
AIRCRAFT / EQUIPMENT X		
ATC / Advisory - TRACON Make Model Name Operating Under FAR Part	SCT Medium Large Transport, Low Wing, 2 Turbojet Eng 91	
PERSON 1		
Function - Flight Crew Function - Flight Crew ASRS Report Number	Captain Pilot Flying 2180991	
EVENTS		
Anomaly Anomaly Anomaly Detector - Person Result - General Result - Flight Crew	ATC Issue - All Types Deviation - Speed - All Types Deviation / Discrepancy - Procedural - FAR Flight Crew Work Refused Requested ATC Assistance / Clarification	

Two times on the same day, when departing SNA on the SID (taking off 20R on HHERO3), ATC assigned speed 280 while climbing through 6000 feet. We complied, thinking perhaps because we were further than 12 miles from the mainland, it was permitted.

I thought this was out of the ordinary and called LA ATC on the phone, The person who answered said that speed above 250 was sometimes assigned below 10,000' for operational need.

While speaking with other pilots, we can't find definitive proof that assigning a speed above 250 below 10,000' is permitted.

This same thing happened again 2 days ago in the same place. We refused and didn't comply until reaching 10,000'.

SYNOPSIS

Corporate captain reported ATC gave instructions to fly at 280 knots below 10,000 feet on two separate occasions at this location.	